



NRA

## DEVON AREA INTERNAL REPORT

**AN INVESTIGATION INTO POSSIBLE  
CAUSES OF POOR WATER QUALITY AT  
BLAKEWELL BRIDGE (R30A001) ON THE  
BRADIFORD WATER.**

**DECEMBER 1995  
DEV/E/19/95**

**Author: P ROSE  
INVESTIGATIONS TECHNICIAN**

*National Rivers Authority  
South Western Region*



**G R Bateman  
Area Manager (Devon)**

614.77  
NAT

c. 1 50

AJTE

## **AN INVESTIGATION INTO POSSIBLE CAUSES OF POOR WATER QUALITY AT BLAKEWELL BRIDGE (R30A001) ON THE BRADIFORD WATER.**

### **1. INTRODUCTION**

The Bradiford Water is a small tributary of the River Taw and rises west of Berry Down in north Devon. The river flows south then south west for approximately 15 km before its confluence with the River Taw estuary.

The single routine chemical monitoring site, Blakewell (R30A001 at NGR SS 5663 358), is designated under the EC Directive for the Protection of Salmonid Fish and has a current River Ecosystem Use (RE) Class target of 2. However, it is being considered that in the future this target will be increased to an RE class of 1.

### **2. TERMS OF REFERENCE**

#### **2.1 OBJECTIVES**

A request was received from Regional Quality Planning to briefly investigate the area above Blakewell. Although current classification will meet the River Quality Objective (RQO) of RE class 2, if the class is calculated on the future proposed Environmental Quality Standards (EQS) for a class 1, the site would fail.

In this study, the area concerned has been investigated to identify possible cause of poor water quality of the watercourse.

#### **2.3 PROJECT TEAM**

T. Cronin (Project Leader)  
P. Rose (Project Manager, author)

### **3. METHOD**

1. Analysis of routine water quality data to establish any trends and / or relationships between water quality and other factors such as rainfall and drought.
2. Talk to Water Quality Officers to ascertain possible problem areas.
3. Carry out a catchment investigation using sewage fungus as a primary indicator to track down problem areas.
4. Inform the Water Quality Officer for the area of any major inputs that are causing impact in the watercourse.



## 4. RESULTS

### 4.1 HISTORIC RESULTS

Analysis of routine water quality data taken at Blakewell Bridge between the period of 01 January 1992 and 08 November 1995 (see APPENDIX I) show the following exceedances (using RE class 1 EQS's, see APPENDIX II):

BOD 3 (from 46 samples taken) EQS =2.5 mg/l as 90 %-ile  
Dissolved Oxygen 1 (from 45 samples taken) EQS =80 % saturation as 10 %-ile  
The exceedances are generally associated with rainfall.

### 4.2 INVESTIGATION RESULTS

See proformas enclosed.

## 5. DISCUSSION

Of the areas tracked down one, Collacott Farm, appears most likely to be the probable cause of elevated BOD levels in the Bradiford Water during rainfall events. The sewage fungus present within the farm tributary was thick and had formed large floating colonies.

During the Farm Campaign of early 1995, Collacott Farm was identified as having a problem with cattle slurry overflowing. It may be that either remedial work has not yet been carried out or improvements are insufficient or not managed properly. The Water Quality Officer (WQO) for the area has been informed and will be visiting the farm.

The tributary from Viveham Farms contained a total ammonia concentration above the EQS (0.64 mg/l in the sample). Impact was very localised although it is possible that under very heavy rainfall, run-off may contribute to chemical impact at Blakewell Bridge.

Viveham Farm was also noted in the Farm Campaign though mainly due to poor management practices

## 6. CONCLUSION

1. Collacott Farm has an illegal discharge that has the potential to impact at the downstream routine monitoring point Blakewell Bridge during heavy rain.
2. The discharge from Collacott Farm is illegal and needs to be controlled.
3. Viveham, Wheaten and Higher Muddiford farms have the potential to cause localised impact due to farm run-off in wet weather

7. **RECOMMENDATIONS**

1 Collacott Farm to be visited by the WQO.

**ACTION:WQO**

**SITE:** Collacott Farm

**WATERCOURSE** Tributary of Colam Stream

**NGR** SS 5567 4170 (Tributary locality) SS 5625 4182 (problem locality)


**EVIDENCE OF WATER QUALITY PROBLEM**

Tributary covered with 100% sewage fungus downstream of the farm. The stream tributary leading down from the Collacott Farm smelt of farm effluent. Sewage fungus apparent to approximately 2 km downstream in the Colam Stream.

Site Description	Site No.	Total Ammonia mg/l	BOD mg/l
Tributary D/S	1	2.0	17.5
Farm ditch	2	50.0	643
Tributary U/S ditch	3	<0.03	<1.0

**SOURCE OF PROBLEM:**

Farm effluent was directly entering the head waters of the tributary. A land drain with clear running water was taken as the upstream site.



**IMPLICATIONS:**

Collacott Farm has the potential to cause chemical impact of the Bradford water downstream and possibly at the routine monitoring site at Blakewell during heavy rainfall.

**RECOMMENDATIONS:**

The Water Quality Officer has been notified and will be visiting the farm.



**SITE:** Viveham Farms

**WATERCOURSE** Tributary of Bradiford water


**NGR** SS 5745 3895

**EVIDENCE OF WATER QUALITY PROBLEM**

Tributary covered with approximately 10% sewage fungus downstream of the farm tributary. Chemical samples indicated no EQS exceedance within the receiving tributary but a total ammonia concentration of 0.64 mg/l (EQS =0.25 mg/l as 95 %-ile) in the farm tributary.

**SOURCE OF PROBLEM:**

The small tributary leading down from the Viveham Farms was running turbid at the source but almost clear at the confluence downstream. Sewage fungus was detected downstream of the tributary for approximately 1 km (from 10 % cover to trace levels ). General run-off was entering the small tributary from the farm area.



**IMPLICATIONS:**

Although the receiving water samples taken did not exceed EQS's, it is possible that under heavy rain Viveham Farms may pose a problem.

**RECOMMENDATIONS:**

The Water Quality Officer to be aware of the potential problem that run-off from Viveham Farms may have on the Bradiford Water during wet weather.



**SITE:** Higher Muddiford Farm

**WATERCOURSE** Tributary of Bradiford water


**NGR** SS 5630 3820

**EVIDENCE OF WATER QUALITY PROBLEM**

Tributary very turbid, entering clear water stream.  
Chemical samples indicated no EQS exceedance of tributary or receiving water.

**SOURCE OF PROBLEM:**

Higher Muddiford Farm is directly adjacent to road. Road drains empty into near-by ditch and into a muddy tributary area which then enters stream as above. Farm waste evident along road; very likely that farm run-off will enter the watercourses during wet weather.



**IMPLICATIONS:**

Although the samples taken did not exceed EQS's, it is possible that during wet weather, farm waste run-off may enter the river and cause localised impact.

**RECOMMENDATIONS:**

The Water Quality Officer to be aware of the potential problem that run-off from Higher Muddiford Farm may have on the Bradiford Water during wet weather.



**SITE:** Whiddon Farm

**WATERCOURSE** Tributary of Bradiford water

**NGR** SS 5555 3873

**EVIDENCE OF WATER QUALITY PROBLEM**

Tributary covered with approximately 70% sewage fungus .  
Chemical samples indicated no EQS exceedance of tributary or receiving water.

**SOURCE OF PROBLEM:**

A small ditch at Whiddon Farm was contaminated with farm effluent which in turn was entering a small tributary. The sewage fungus cover present suggests this to be a chronic problem, however, from the chemical results (no impact), a minor one.




**IMPLICATIONS:**

Although the samples taken did not exceed EQS's, it is possible that due to the locality of the water course to the farm, during wet weather, some effluent may enter the river and cause localised impact.

**RECOMMENDATIONS:**

The Water Quality Officer to be aware of the potential problem that run-off from Whiddon Farm may have on the Bradiford Water during wet weather.





**APPENDIX I**

## ANALYTICAL SUMMARY OF--

## SPALIFORD WATER AT BLANWELL

Date	Time	Type	Pump	Mat	OXYGEN DISS % SATN	BOD ATU MG/L	AMMON- IA MG/L N	SILICE SUSP MG/L
100192	1122	SCMR	BF			1.8	0.07	82
140292	1230	SCMR	BF		95	1.4	0.07	11
150392	1125	SCMR	BF		99	1.4	0.05	9
270492	1350	SCMR	BF		100	1.2	0.06	3
270592	1400	SCMR	BF		95	1.3	0.06	3
290692	1415	SCMR	BF		94	1.3	0.05	3
010992	1315	SCMR	BF		94	1.1	0.05	2
230892	1355	SCMR	BF		95	1.3	0.05	8
290992	1455	SCMR	BF		94	1.3	0.03	7
291092	1330	SCMR	BF		97	1.4	0.02	42
121192	1120	SCMR	BF		91	1.7	0.05	48

Type "C" to Continue, "P" for previous screen, "9" to Quit ( )

TYPE

ONLINE

READ

## ANALYTICAL SUMMARY OF--

## BRADIFORD WATER AT BLANWELL

Date	Time	Type	Pump	Mat	OXYGEN DISS % SATN	BOD ATU MG/L	AMMON- IA MG/L N	SILICE SUSP MG/L
041292	1320	SCMR	BF		95	1.6	0.07	52
110192	1345	SCMR	BF		98	1.3	0.06	20
090292	1410	SCMR	BF		99	1.3	0.07	8
040392	1300	SCMR	BF		92	2.2	0.07	3
010492	1120	SCMR	BF		105	1.6	0.05	2
270492	1200	SCMR	BF		97	1.7	0.06	2
060692	1150	SCMR	BF		92	1.3	0.05	2
020792	1400	SCMR	BF		86	1.1	0.10	1
090892	1030	SCMR	BF		87	1.5	0.05	11
100992	1430	SCMR	BF		100	2.2	0.17	12
081092	1425	SCMR	BF		82	1.5	0.04	12

Type "C" to Continue, "P" for previous screen, "9" to Quit ( )

TYPE

ONLINE

READ



ANALYTICAL ELEMENTS

SACRIFICED WATER AT BLAKEWELL

Date	Time	Type	Rate	Flow	Temp	Pressure	Flow	Temp	Pressure
091199	1505	50MR	2F	99	1.1	0.05	9		
171199	1040	50MR	2F	90	1.1	0.05	17		
100194	1305	50MR	2F	99	1.1	0.05	12		
040294	1340	50MR	2F	100	1.6	0.04	12		
130294	1410	50MR	2F	97	2.5	1.24	31		
250394	1500	50MR	2F	95	1.4	0.05	13		
120594	1155	50MR	2F		1.5	0.02	3		
140694	1620	50MR	2F	94	1.4	0.07	11		
250794	1035	50MR	2F	94	2.7	0.02	11		
140994	1310	50MR	2F	90	1.9	0.11	13		
1061094	1025	50MR	2F	104	1.7	0.04	9		

Type "C" to Continue, "P" for previous screen, "E" to Exit

TYPE

ONLINE

READY

ANALYTICAL SUMMARY OF

BRACKISH WATER AT BLANKWELL

Date	Time	Type	Temp	DO	Chlorine	Alkalinity	Hardness	Calcium	Magnesium	Ammonia Nitrogen	Total Solids
10/10/55	1430	Surface	14.0	9.8	0.1	100	100	1.0	1.0	0.15	1.0
10/11/55	1430	Surface	14.0	9.7	0.1	100	100	1.0	1.0	0.15	1.0
10/12/55	1430	Surface	14.0	9.8	0.1	100	100	1.0	1.0	0.15	1.0
10/13/55	1430	Surface	14.0	9.8	0.1	100	100	1.0	1.0	0.15	1.0
10/14/55	1430	Surface	14.0	9.8	0.1	100	100	1.0	1.0	0.15	1.0
10/15/55	1430	Surface	14.0	9.8	0.1	100	100	1.0	1.0	0.15	1.0
10/16/55	1430	Surface	14.0	9.8	0.1	100	100	1.0	1.0	0.15	1.0
10/17/55	1430	Surface	14.0	9.8	0.1	100	100	1.0	1.0	0.15	1.0
10/18/55	1430	Surface	14.0	9.8	0.1	100	100	1.0	1.0	0.15	1.0
10/19/55	1430	Surface	14.0	9.8	0.1	100	100	1.0	1.0	0.15	1.0
10/20/55	1430	Surface	14.0	9.8	0.1	100	100	1.0	1.0	0.15	1.0

ANALYSIS BY THE WATER PURIFICATION DISTRICT, BLANKWELL, TEXAS

ANALYTICAL SUMMARY CP1-

BRADFORD WATER AT BLAISEWELL

CLYVEN 301      W/WHEN-      BL-100  
DISE      ATD      Y5      215F  
W/SAFN M37L      2 M37L N      M37L

Date	Time	Pump	Mat
201009	1015	SCMR	2F
091109	1200	SCMR	2F

91	3.8	0.00
92	1.24	0.06

Type "C" to Continue, "P" for previous screen, "Q" to Quit ( )

ONLINE      READY



**APPENDIX II**

TABLE 1 : STANDARDS FOR THE FIVE RIVER ECOSYSTEM USE CLASSES

Use Class	DO % sat 10%ile	BOD (ATU) mg/l 90%ile	Total Ammonia mgN/l 95%ile	Un-ionised Ammonia mgN/l 95%ile	pH 5%ile & 95%ile	Hardness mg/l CaCO <sub>3</sub>	Dissolved Copper µg/l 95%ile	Total Zinc µg/l 95%ile	Class Description
1	80	2.5	0.25	0.021	6.0 - 9.0	≤ 10 > 10 and ≤ 50 > 50 and ≤ 100 > 100	5 22 40 112	30 200 300 500	Water of very good quality suitable for all fish species
2	70	4.0	0.6	0.021	6.0 - 9.0	≤ 10 > 10 and ≤ 50 > 50 and ≤ 100 > 100	5 22 40 112	30 200 300 500	Water of good quality suitable for all fish species
3	60	6.0	1.3	0.021	6.0 - 9.0	≤ 10 > 10 and ≤ 50 > 50 and ≤ 100 > 100	5 22 40 112	300 700 1000 2000	Water of fair quality suitable for high class coarse fish populations
4	50	8.0	2.5		6.0 - 9.0	≤ 10 > 10 and ≤ 50 > 50 and ≤ 100 > 100	5 22 40 112	300 700 1000 2000	Water of fair quality suitable for coarse fish populations
5	20	15.0	9.0						Water of poor quality which is likely to limit coarse fish populations