NRA-South West 454

DEVON AREA INTERNAL REPORT

AN INVESTIGATION TO DETERMINE IF SOUTH MOLTON STW IS THE CAUSE OF ELEVATED COPPER AND ZINC CONCENTRATIONS DOWNSTREAM IN THE RIVER MOLE

> DECEMBER 1995 DEV/E/18/95

Author: P ROSE INVESTIGATIONS TECHNICIAN

> National Rivers Authority South Western Region

NRA

G R Bateman Area Manager (Devon)

c. 1 sc

AN INVESTIGATION TO DETERMINE IF SOUTH MOLTON STW IS THE CAUSE OF ELEVATED COPPER AND ZINC CONCENTRATIONS DOWNSTREAM IN THE RIVER MOLE.

614.77/NAT NATIONAL RIVERS AUTHORITY An investigation to determine if South Milton AJTF c. 1 so .00

1. INTRODUCTION

The River Mole is the major tributary of the River Taw and rises on Exmoor at Darlick Moors and flows south west for approximately 34 Km before its confluence with the River Taw at Junction Pool.

The River Mole has a River Ecosystem Use Class target of 2. For the purpose of this desk study, the Environmental Quality Standards (EQS's) appropriate for the protection of salmonid fish will be adopted for all sites investigated (see APPENDIX I).

2. TERMS OF REFERENCE

2.1 OBJECTIVES

A request was received from Regional Quality Planning to investigate high concentrations of dissolved copper and total zinc recorded downstream of South Molton STW (WSTW3280B) during 1994.

The aim of this investigation is to determine if metal concentrations in the final effluent are causing the EQS at the downstream site of South Molton STW as specified in the 'Ups and Downs' progamme.

2.3 PROJECT TEAM

T. Cronin (Project Leader) P. Rose (Project Manager, author)

3. METHOD

- 1. Collection of water samples from South Molton STW final effluent and localised area on same dates over a period of months to build a comparable data set.
- 2. Analysis of routine water quality data to establish any trends and / or relationships between water quality and other factors such as rainfall and drought.



4. **RESULTS**

4.1 HISTORIC DATA

Analysis of routine water quality metals data taken downstream of South Molton STW (WSTW3280B) between the period of 01 January 1994 and 31 December 1994 (see APPENDIX II) show the water quality to fail both EQS's:

Total zinc12 samplesAnn. average0.016 mg/lEQS 0.008 mg/lDissolved copper12 samplesAnn. average0.00275 mg/lEQS 0.001 mg/l

The total hardness average for 1994 was 43.2 mg/l, the lowest band.

Samples taken from the final effluent at South Molton STW (WSTW3280FE) and upstream at site (WSTW3280A) during 1994 were analysed for dissolved copper and total zinc content. The data set for these sites during 1994 is limited to 6 samples. The site WSTW3280A (immediately upstream of the STW) fails the EQS for dissolved copper:

Total zinc	6 samples	Ann. average	0.0025 mg/l	EQS 0.008 mg/l
Dissolved copper	6 samples	Ann. average	0.0022 mg/l	EQS 0.001 mg/l

The total hardness average for the samples taken upstream of the works discharge point during 1994 was 42.2 mg/l, the lowest band.

The only other routine monitoring site where water samples are regularly analysed for metals is above North Molton STW (R30F001). This site also fails the EQS for dissolved copper.

Total zinc	12 samples	Ann. average	0.0036 mg/l	EQS 0.008 mg/1
Dissolved copper	12 samples	Ann. average	0.0032 mg/l	EQS 0.001 mg/l

The total hardness average for the samples taken upstream of the works discharge point during 1994 was 35.6 mg/L the lowest band.

4.2 INVESTIGATION DATA

For data collected during the period of the investigation (14 June 1995 to 31 October 1995) see Figure 1. For the purpose of this study, the pass or fail at each site has been calculated on the hardness of each sample taken.

5. DISCUSSION

Failure of the EQS at WSTW3280B for dissolved copper during 1994 was due to all samples containing concentrations marginally above the standard. The data set for above the discharge point also contains concentrations similarly above the EQS.

The 1994 failure of the total zinc standard downstream of the works was due to one sample containing an elevated concentration (0.131 mg/l). No corresponding sample was taken from the effluent or immediately upstream; as such, this exceedance cannot be attributed to the STW discharge.

The data set obtained during the investigation has enabled direct comparison to be made of water quality up and down of the STW whilst taking the quality of the effluent into account.

Firstly, although there were concentrations of copper and zinc above current levels of detection (LoD) within the discharge (total Zinc LoD 0.005 mg/l, dissolved copper LoD 0.0025 mg/l), there was no appreciable impact downstream of the works at R30F003 (see Figure 1).

During the investigation, the concentrations of dissolved copper increased by approximately 60 % at sites upstream of South Molton STW discharge up to and including Newbridge (above North Molton, see Figure 1, comparison of data from R30F003 and Newbridge). Above this area, the concentration immediately falls to below detection limits.

The area in question is known for historic mines. Indeed, upstream of the Newbridge site and D/S of the Mines Bridge site there are old mine workings and shafts near the watercourse. It is very probable that this combined with natural geology is causing the elevated metal concentrations downstream.

Many exceedances within the data set collected during the investigation were due to a combination of low hardness band and the LoD. If a sample falls into the lowest hardness band and contains copper concentration below the LoD, the sample will effectively exceed the standard whether taken at face value or even half face value. The implications of this are that a site will fail the standard for dissolved copper if all the samples contain concentrations below the LoD and the site is placed in the lowest hardness band.

CONCLUSIONS


- 1. The exceedances of EQS's for Total Zinc and Dissolved Copper at WSTW3280B could not be attributed to South Molton STW.
- 2 Samples taken from sites upstream of South Molton STW contained concentrations of total zinc and dissolved copper above those recorded downstream of the final effluent point.
- 3 Increases of total zinc and dissolved copper concentrations in the upper reaches of the River Mole catchment are probably due to historic mine activity / natural geology.

4 Low hardness banding and relatively high detection limits of copper and zinc may result in EQS exceedance even when samples contain concentrations below detection limits.

7. **RECOMMENDATIONS**

- 1. Continue monitoring for dissolved copper and total zinc at routine monitoring sites on the River Mole.
- 2. Enquire as to possibility of setting detection limits at or below strictest water quality standards for appropriate substances.

Figure 1. Map of the River Mole showing investigation monitoring sites and results.



APPENDIX I

EQSs FOR LIST II SUBSTANCES (INLAND WATERS) (I)

Table 5 continued

Paraineter	Units	Valu	ie (3)	llardness (me	Status (2)	
		A Sid B Sid		(mcO,/l)		
Lead	μg Ph/I	4	50	0 to 50	AA,D	
Ecau	ME TIT	10	125	50 to 100	~~.v	
		10				
		1	125	100 to 150		
		20	250	150 to 200		
1		20	250	200 to 250	1	
		20	250	> 250		
Chromium	μg Cr/l	5	1.50	0 10 50	AA.D	
		10	175	50 to 100		
		20	200	100 to 150		
		20	200	150 10 200		
		50	250	200 10 250		
		. 50	250	>250		
Zinc	μg Zn/l o	8	75	0 to 50	ΛΑ.Τ	
		50 .	175	50 to 100		
		75	250	100 to 150		
		75	250	150 to 200		
		75	250	200 to 250		
		125	500	>250		
Copper	μg Cu/l		1	0 to 50	AA,D	
		6	6	50 to 100		
		10 .	10	100 to 150		
		10	10	150 to 200		
		10	10	200 to 250		
		28	28	> 250		
Niekal	NO ALL	50		0 (0	44.0	
Nickel	µg Ni/I	50	50	0 to 50	AA,D	
1		. 100	100	50 to 100		
		150	150	100 to 150		
		150	150	150 to 200		
	- +	200	200	200 to 250		
the state of the second state of the		200	200	>250 .	1 . HA	
Arsenic	µg As/l	50) - (All	AA,D.	
Boron	µg ВЛ	: 200	00	All	AA,T	
Iron	µg Fe/I	.100	00	All	AA,D	
HI STATE	pH values v/	6 to	in a	- Y All	95% of samples	
1 5 5 5 5 1 h h h				12 14 14 13		
Vanadium	μg V/I	20	20	0 to 200	AA.T	
	a property	60	60	200+		
Tributyltin	μg/l	0.0	2	ILA	M,T	
Triphenyllin	μg/l	0.02 ·		A11 -	M,T	
Polychlorochlormethyl-	μg/l	0.0	5	All	T. 95% of samples	
ulphonamidodiphenyl ether					the second se	
PCSDs)	2.35			1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	1	
Sulcofuron	μεΛ	25		All	T, 95% of samples	
	-	_				
Flucofuron	μg/Ι	. 1.0		IIA	T, 95% of samples	
Permethrin	μg/l	0.0	1	All .	T, 95% of samples	
Cyfluthrin	μg/1	0.00		All.	T. 95% of samples	
the second se						

EQSs FOR LIST II SUBSTANCES (TIDAL WATERS)

Table 5 continued

		* U	
Parameter	Units	Value (1)	Status
Lead	µg Pb/I	25	A'A.D
Chromium	μg Cr/l	15	AA,D
Zinc	μg Zn/l	40	AA,D
Copper	μg Cu/l	5	AA,D
Nickel	μg Ni/l	30	AA,D
Arsenic	µg As/l	25	AA,D
Boron	μg B/I	7000	AA,D
Iron	µg Fe/l	1000	AA,D
рН	pH values	6 to 8.5 (3)	95% of samples
Vanadium	μg V/I	100	AA,T
Tributyltin	μg/l	0.002	M,T
Triphenyltin	μg/l	0.008	M,T
Polychlorochlormethyl- sulphonamidodiphenyl ether (PCSDs)	με/۱	0.05	T. 95% of samples
Sulcofuron	μg/l	25	T, 95% of samples
Flucofuron	μg/l	1.0	T, 95% of samples
Permethrin	μg/l	0.01	T, 95% of samples
Cyfluthrin	μg/l	0.001	T, 95% of samples

Notes:

(1) (2) National environmental quality standards recommended for the UK.

AA=Annual Average; D=Dissolved; T=Total; M=Maximum Allowable Concentration

(3)

A Std denotes standards for the protection of sensitive aquatic life B Std denotes standards for the protection of other aquatic life

APPENDIX II

ANALYTICAL SUMMARY OF :-

RIVER MOLE BELOW SOUTH MOLTON STW DIS FEATURE NOT AVAILABLE

Type DISS TOTAL TOTA Date Time Purp Mat MG/L MG/L MG/L	L 0.6 8.9	
040394 0945 SQMR 2F 0.0020 0.131 4	0.6	
270494 1000 SQMR 2F 0.0030 0.004 4	2.3	
	6.4	
	4.7	
181094 0800 SQMR 2F 0.0030 0.003 4	5.2	
071194 1225 SQMR 2F 0.0030 0.005 4	7.3	

Type "C" to Continue, "P" for previous screen, "Q" to Quit () TYPE ONLINE READY

ANALYTICAL SUMMARY OF :-

RIVER MOLE BELOW SOUTH MOLTON STW DIS FEATURE NOT AVAILABLE

		COFFER	ZINC	HARDNS
	Туре	DISS	TOTAL	TOTAL
Date		MG/L	MG/L	MG/L

251194 0930 SQMR 2F 0.0020 0.004 40.6

Type "C" to Continue, "F" for previous screen, "Q" to Quit () TYPE ONLINE READY