



Aerial photograph taken May 1995. Bear Brook flood storage area in centre

## AYLESBURY FLOOD ALLEVIATION SCHEME



#### Typical flooding in Aylesbury prior to works

Aylesbury a rapidly expanding town has a history of flooding, most significantly in 1947 and most recently in 1987, when large parts of the town were flooded, particularly around the Stocklake area.

Responsibility for the primary river flood defences was passed to the Thames Region of the Environment Agency on 1st April 1996. The Agency is an independent public body charged with safeguarding and improving the natural water environment.

In association with the Aylesbury Vale District Council (AVDC) and following an extensive study of flood records, local geography and land development, a scheme to protect Aylesbury from flooding was instigated.

Following extensive research and the preparation of a computer model, a flood relief scheme was prepared to cater for future development and provides protection from a 1 in 100 flood event.

Each flood event is analysed using current and historic flood records and is given a 'return' period. A 1 in 100 flood event will occur on average once every 100 years with a 2% chance of a flood of that intensity happening in any one year.

To avoid extensive and highly disruptive works within the town a strategy was developed to intercept flood waters before they actually reached the town. To help promote the scheme and keep concerned local residents informed of developments regular newsletters were issued, public displays and meetings were held. The main elements of the scheme consisting of two large flood storage ponds, were incorporated into the Aylesbury local plan.

Completed in October 1994, the works were jointly funded by the Agency and AVDC together with grant-in-aid from the Ministry of Agriculture, Fisheries and Flood. The total cost exceeded £2m including a £0.16m contribution from AVDC.

### AYLESBURY FLOOD ALLEVIATION SCHEME



# Flood storage ponds construer were the key to the success safely contained by the char to 3.8 and 0.7 m³/s respective.

BEAR BROOK AND

FLOOD STO

The reduction is achieved 30,000m<sup>3</sup> of flood storage. Thence will be subject to regular.

The flows are regulated embankments. The diversio for the pond on the Bear Br

The Agency are committeenvironment in all their wor

The opportunity was taken and to enhance and create conservation and amenity Dragonflies, Bats, Water Vo



Bear Brook flume view looking downstream



Bear Bro storag during

#### BEAR BROOK SYPHON



Upstream Inlet

#### STOCKLAKE BROOK PAGE AREAS

of the scheme. They are designed to only pass on flows which can be nels through Aylesbury. In the 1 in 100 year event, flows are reduced ely, this representing reductions in peak flows of 27% and 53%.

by providing clay embankments which provide up to 105,000 and the size of the ponds is such that both are classified as Reservoirs and lar inspection.

by specially designed flumes contained within the downstream and extension of the surface water drainage system was necessary took.

ed to improving wild-life habitats and conserving the natural

with the Bear Brook storage pond to carry out extensive landscaping emporary and permanent wetlands. This significantly improved the value of the land and has already created valuable habitats for es, Frogs, Grey Herons, Black Headed Gulls and many others.

ok flood e area minor od



Problems had long been encountered where the Bear Brook passes under the Aylesbury Arm of the Grand Union Canal. Known as the Bear Brook syphon and permanently submerged, the syphon (or culverts) were difficult to inspect and prone to blockage with a build up of flood debris preventing the watercourse flowing freely.

The work involved constructing a new Portland stone overfall upstream of the structure which, in combination with the Bear Brook regrading, provides for clear passage of water. The opportunity was taken to fully refurbish the syphon and the approach and exit channels. This is believed to be for the first time since the canal was built.

#### BEAR BROOK REGRADING



Typical view prior to works




Similar view after regrading and lowering of water level

Historically a weir associated with a disused mill downstream of the syphon acted as a major obstruction to flows often resulting in high water levels in the adjoining industrial estates. By removing the weir and regrading 500 metres of the Bear Brook the flood capacity was greatly increased. During the works the bed was lowered by approximately 1.5 metres, however, great care was taken to recreate the original environment which is clearly demonstrated on the accompanying photographs.

#### Miscellaneous Works

Although extensive channel works within the town were not possible the following local improvements were carried out. Local dredging, removal of obstructions and the provision of splitting weirs which prevent the canal from draining during period of low flow in the brook.





STOCKLAKE BROOK

Produced by: Reading Design & Print (0118) 942 2295

THAMES REGION

Kings Meadow House, Kings Meadow Road, Reading RG1 8DQ